

## **Gold Ink Handling Procedures**

JG-012UA (50wt% aerosol jet ink – UA ink)

JG-014UA (50wt% aerosol jet ink – UA ink)

JG-106 (40wt% inkjet ink)

JG-107 (30wt% inkjet ink)

- Ink should remain refrigerated (2 – 10 °C) unless in use.
- Ink should not come into contact with aluminum or anodized aluminum. Contact with these surfaces will cause destabilization.
- For assistance or questions contact:
  - o Dave Pope – [dave.pope@novacentrix.com](mailto:dave.pope@novacentrix.com)
  - o Sze-Ming Lee – [sze-ming.lee@novacentrix.com](mailto:sze-ming.lee@novacentrix.com)

May 13, 2022